

Conversion Formulas

inch x 25.4 = mm
foot x 304.8 = mm
mile x 1.609 = km

mm x 0.03937 = inch
meter x 39.37 = inch
km x 0.6214 = mile

Fahrenheit to Celsius: $^{\circ}\text{C} = ^{\circ}\text{F} - 32 \times 5 \div 9$

Celsius to Fahrenheit: $^{\circ}\text{F} = ^{\circ}\text{C} \times 9 \div 5 + 32$

Mill and Lathe Conversions

To Find:

Formula:

Revolutions Per Minute	RPM	=	$(\text{SFM} \times 3.8197) \div D$
Surface Feet Per Minute	SFM	=	$\text{RPM} \times D \times 0.2618$
Surface Meters Per Minute (Metric)	SMPM	=	$\text{SFM} \times 0.3048$
Inches Per Minute Milling Feedrate	IPM	=	$\text{FPT} \times T \times \text{RPM}$
Feed Per Tooth Mill	FPT	=	$\text{IPM} \div (T \times \text{RPM})$
Feed Per Revolution	FPR	=	$\text{IPM} \div \text{RPM}$
Inches Per Minute <i>Lathe</i>	IPM	=	$\text{IPR} \times \text{RPM}$
Metal Removal Rate	MMR	=	$W \times d \times F$
Advance Per Revolution (Inches)	ADV/R	=	$F \div \text{RPM}$

Threads

Mill Tapping Feedrate	IPM	=	$1 \div \text{TPI} \times \text{RPM}$
<i>Lathe</i> Threading Feedrate (Thread Lead)	IPR	=	$1 \div \text{TPI}$
Tap Drill Size	=	Major Dia. of Tap -	$\frac{\% \text{ of Thread Height} \times .01299}{\text{TPI}}$
Percent of Full Thread	=	$\text{TPI} \times$	$\frac{\text{Major Dia. of Tap} - \text{Drill Dia.}}{.01299}$
Mill Tapping Feedrate (Metric)	=	$1 \div \text{RPM} \times$	Metric Pitch
Tap Drill Size (Metric)	=	Tap Major Dia. (mm) -	$\frac{\% \text{ of Thread Height} \times \text{Metric Pitch}}{76.980}$
Percent of Full Thread (Metric)	=	$\frac{\text{Basic Major Dia. (mm)} \times 76.980 - \text{Drilled Hole (mm)}}{\text{Metric Pitch}}$	

Miscellaneous

Radius of Circle	=	$\text{Circumference} \times 0.159155$
Diameter of Circle	=	$\text{Circumference} \times 0.31831$
Circumference of Circle	=	$D \times 3.1416$
Area of Circle	=	$R^2 \times 3.1416$
Cutting Time in Minutes (Mill)	=	$L \div \text{IPM}$
Cutting Time in Seconds (Lathe)	=	$\frac{\text{Distance to go} \times 60 \text{ sec}}{\text{IPR} \times \text{RPM}}$

Abbreviations and Measurement Units

D	=	Diameter of Milling Cutter or Lathe Part	SFM	=	Surface Feet per Minute
d	=	Depth of Cut	SMPM	=	Surface Meters per Minute
FPR	=	Feed per Revolution (in Inches)	T	=	Number of Teeth in the Cutter
FPT	=	Feed per Tooth (in Inches)	TPI	=	Threads per Inch
IPM	=	Inches per Minute (Table Travel Feedrate)	W	=	Width of Cut
IPR	=	Inches per Revolution	$^{\circ}\text{C}$	=	Degrees Celsius
L	=	Length of Cut (Inches)	$^{\circ}\text{F}$	=	Degrees Fahrenheit
RPM	=	Revolutions per Minute (Spindle Speed)			